SAP E & C P TO I CONVERTER SET UP (PRODUCT CODE: SAP – 18A)





The **P to I Converter Trainer** (**Product Code: SAP – 18A)** give an idea regarding the operation of Pneumatic to Electric conversion.

P TO I CONVERTER SET UP (SAP – 18A)

Technical Specification: -No. Item Name **Technical Specifications** P/I Converter-1 Input: 3-15 PSI Output: 4-20 mA Range: 0- 2.1 Kg/cm², with Pressure Gauge 2 Precision APR-3 Digital Current Indicator-Supply: 1 g 230 VAC, Range : 0-20 mA 4 Pressure Vessel-Capacity : 2.1 Kg/cm² 5 Pressure Gauge-Range : 0-2.1 Kg/cm²

Features-

- Compact Ergonomic Design.
- User Friendly, Self Explanatory Systems.
- Robust Construction.
- Ms Powder coated frame.
- Training Manual for Operation Ease.

Range of Experiments-

Study of P to I Converter Setup.

System Specifications-

- Digital Current Indicator with 3 ½ Digital Display
- P/I Converter Input : 3-15 PSI Output : 4-20mA
- Pressure Vessel Capacity 2.1 Kg/ cm²
- Precision Air Filter Regulator with Pressure Gauge

Services Required-

- Electric supply 1φ 230 V AC, 50 Hz.
- Suitable compressed air supply (0-4 Kg/cm²)

Note-

All descriptive matter and illustrations are intended to give only a general idea of the equipment Detailed specifications may be altered at the company's discretion without any notice.



Page: 1 of 1